

CONTENTS

	Page
I. INTRODUCTION	1-1
1.1 Introductory Remarks	1-1
1.2 Geography and History	1-3
1.3 Geologic and Tectonic Setting	1-4
1.4 Seismologic Setting	1-6
1.5 Seismic-Resistant Design Practice	1-12
1.6 Building Construction	1-16
1.6.1 Architectural Influences in Algeria	1-16
1.6.2 Building Construction in El-Asnam	1-17
II. SEISMOLOGIC AND GEOLOGIC FEATURES	2-1
2.1 Location, Magnitude, Intensity, and Pattern of Shaking	2-1
2.2 Surface Faulting	2-4
2.3 Aftershocks	2-9
2.4 Ground Motion Records	2-10
2.5 Site Soil Conditions	2-11
III. EARTHQUAKE EFFECTS	3-1
3.1 General Description of Damage	3-1
3.2 Surface Faulting	3-4
3.2.1 Aqueducts and Irrigation Distribution Systems	3-4
3.2.2 Buildings	3-4
3.2.3 Highways and Railroads	3-8
3.3 Tectonic Subsidence and Tilting	3-10
3.4 Ground Failure	3-10
3.4.1 Liquefaction	3-10
3.4.2 Landslides	3-15
3.4.3 Differential Settlement	3-18
3.5 Strong Ground Motion (Shaking)	3-20
3.5.1 Hospitals, Schools, Fire and Police Stations, Administrative Buildings, and Small Commercial and Residential Buildings	3-20
3.5.2 Large Industrial and Commercial Buildings	3-31
3.5.3 Transportation Facilities	3-34
3.5.4 Bridges	3-34
3.5.5 Utilities (Lifelines) in El-Asnam	3-35
3.5.6 Dams	3-36
3.5.7 Indirect Effects	3-36
3.6 CTC Program to Evaluate Damage	3-41

IV.	IMPLICATIONS OF BUILDING DAMAGE: CASE STUDIES	4-1
4.1	General Evaluation	4-1
4.1.1	Poor Conceptual Design (Building Configuration and Structural Layout) for Seismic-Resistant Buildings	4-1
4.1.2	Poor Structural Material	4-14
4.1.3	Use of Nonstructural Elements	4-23
4.1.4	Inadequate Proportioning and Detailing of Structural Elements, Connections, and Supports	4-23
4.1.5	Poor Inspection and Construction Techniques	4-24
4.1.6	Inadequate Building Maintenance	4-24
4.1.7	Concluding Remarks	4-24
4.2	Case Studies: Performance of Two Buildings	4-29
4.2.1	Primary School 5 km East of El-Asnam	4-29
4.2.2	Cité An Nasr Market Complex	4-34
4.3	Probable Causes of Some Major Building Failures	4-41
4.3.1	Buildings Whose Design Was Based on Seismic Code Provisions	4-41
4.3.2	Buildings Whose Design Computations Did Not Include Effects of Seismic Forces	4-43
V.	SOCIO-ECONOMIC ASPECTS	5-1
5.1	Human Aspects of the Disaster	5-1
5.2	Rescue and Relief Operations	5-2
VI.	LESSONS LEARNED, CONCLUSIONS, AND RECOMMENDATIONS	6-1
6.1	Socio-economic	6-1
6.2	Geologic and Tectonic	6-1
6.2.1	Liquefaction	6-1
6.2.2	Landslides	6-2
6.3	Engineering Design and Construction	6-2
6.4	Reconstruction Planning	6-4
6.5	Recommendations	6-5
6.5.1	Public Level	6-6
6.5.2	Scientific and Engineering Level	6-7
	REFERENCES	R-1
	POSTSCRIPT	P-1
	APPENDICES	
A	AS 1955 Recommendations for Building in Seismic Regions	A-1
B	Damage Evaluation Form	B-1
C	Analyses of Seismic Performance of Canopies on a Primary School Building ...	C-1
D	Modifications to Seismic Regulations	D-1
E	Team Personnel	E-1
F	Glossary	F-1